

John D. O'Toole
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003
Telephone (212) 460-2533

June 17, 1981

Re: Indian Point Unit No. 2
Docket No. 50-247

Mr. Boyce H. Grier, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, Pa. 19406



Dear Mr. Grier:

We are in the process of completing our re-evaluation of concrete masonry walls at Indian Point Unit No. 2 as requested in NRC Bulletin No. 80-11.

In order to insure that repairs and modifications to the walls, should they be necessary, meet the appropriate standards, we request the Commission's approval of the criteria and justification for the re-evaluation of concrete masonry walls for Indian Point Unit No. 2, which were submitted to you on February 17, 1981.

This information is being provided pursuant to 10 CFR 50.54(f). Should you or your staff have any questions regarding this matter, please contact us.

Very truly yours,

William P. Bennett
for John D. O'Toole

Subscribed and sworn to
before me this 17 day
of June, 1981.

(Area) we.

THOMAS LOVE
Notary Public State of New York
No. 31-2409638
Qualified in New York County
Commission Expires March 30, 1983

8107070302 810617
PDR ADDCK 05000247
Q PDR

IEH
S/10

cc: U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Division of Reactor Operations Inspection
Washington, D. C. 20555

Mr. T. Rebelowski, Resident Inspector
U. S. Nuclear Regulatory Commission
P. O. Box 38
Buchanan, N. Y. 10511