

## LICENSEE EVENT REPORT

CONTROL BLOCK: [ ][ ][ ][ ][ ][ ] (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	C	O	F	S	V	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	2	0	4			5
7	8	14							15	25										26	30					37	CAT	58	
		LICENSE CODE								LICENSE NUMBER											LICENSE TYPE								

CON'T

REPORT SOURCE: 01 L 6 0 5 0 0 0 2 6 7 7 0 5 0 4 8 1 8 0 6 0 3 8 1 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On Monday, May 4, 1981, at 0840 hours, it was determined that equipment necessary to automatically terminate releases from the Fort St. Vrain liquid waste system and the Reactor Building sump was not operating properly. This constitutes operation in a degraded mode of LCO 4.8.2 and LCO 4.8.3 and is reportable per Fort St. Vrain Technical Specification AC 7.5.2(b)2. No accompanying occurrence. Reportable Occurrences RO 80-52, RO 80-67, and RO 81-013 deal with a related subject area.

0	8											80								
7	8	9	SYSTEM CODE		CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE					COMP SUBCODE	VALVE SUBCODE							
0	9		H	F	(11)	X	(12)	Z	(13)	I	N	S	T	R	U	(14)	E	(15)	Z	(16)
1	2	3	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26

(17) LER NO. REPORT NUMBER [EVENT YEAR] [REPORT NO.] [CODE] [TYPE] [NO.]  
 [8] [1] [ ] [0] [3] [4] [ ] [0] [3] [L] [ ] [0]  
 21 22 23 24 25 26 27 28 29 30 31 32  
 AG. ON FUTURE EFFECT SHUTDOWN ATTACHMENT NRPD-4 PRIME COMP. COMPONENT  
 TAKEN ACTION ON PLANT METHOD SUBMITTED FORM SUB. SUPPLIER MANUFACTURER  
 [X] [18] [Z] [19] [Z] [20] [Z] [21] [ ] [ ] [ ] [ ] [Y] [23] [N] [24] [N] [25] [I] [2] [0] [4] [26]  
 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause was partially plugged sense lines on flow element associated with the flow  
1 1 control valve necessary for terminating releases automatically. Plant Trouble Re-  
1 2 port 4-385 written on April 29, 1981, sense lines cleared on April 30, 1981. Subse-  
1 3 quent testing indicated proper operation of the flow element and auxiliary equipment.

1	4											80	
FACILITY STATUS		% POWER		OTHER STATUS		(30)	METHOD OF DISCOVERY		DISCOVERY DESCRIPTION				(32)
1	5	Z	(28)	0	7	0	(29)	N/A	B	(31)	Sample Analysis		

8 9 10 12 13 44 45 80

ACTIVITY CONTENT  
RELEASED OF RELEASE

1 6 Z (33) Z (34) N/A

AMOUNT OF ACTIVITY (35)

LOCATION OF RELEASE (36)

N/A

PERSONNEL EXPOSURES										
NUMBER			TYPE	DESCRIPTION						
1	7	0	0	0	(37)	Z	(38)	N/A	(39)	

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	3	0	0	0	N/A

8 9		11 12	
TYPE		DESCRIPTION	
1 9	2 42	N/A	

7 8 9 10  
PUBLICITY  
ISSUED DESCRIPTION (45)  
2 0 | N | (44) | N/A  
NRC USE ONLY

8107130284 8106C  
PDR ADDCK 05000267  
S PDR

PHONE: (303) 785-2224

1-800-368-7265