

OFFICIAL COPY

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

May 6, 1981

TELEPHONE: AREA 704
373-4083

81-052-03L

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 1
Docket No. 50-369



Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-369/81-45. This report concerns the operability of various portions of the fire detection system. This incident was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

William O. Parker, Jr.
William O. Parker, Jr. *by JS*

RWO:djs
Attachment

cc: Director
Office of Management and Program Analysis
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. Bill Lavallee
Nuclear Safety Analysis Center
Post Office Box 10412
Palo Alto, California 94303

IE22
5/11

8107200448 810506
PDR ADOCK 05000369
S PDR