

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	C	M	G	S	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4		5											
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35											
LICENSEE CODE															LICENSE NUMBER										LICENSE TYPE										CAT 58				

CON T

0	1	L	6	0	5	0	0	0	3	6	9	7	0	4	1	0	8	1	8	0	5	1	0	8	1	9																		
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35																
REPORT SOURCE															DOCKET NUMBER										EVENT DATE										REPORT DATE									

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 While in Mode 3, initial fuel loading, Train A of the Control Area

0 3 Ventilation System was declared inoperable because the A chiller

0 4 would not start. This is in violation of TS 3.7.6 and is reportable

0 5 per T.S. 6.9.1.13 (b). Since no overheating occurred and a redundant

0 6 Train was operable, the health and safety of the public were not affected.

0 7

0 8

0	9	A	A	11	A	12	C	13	1	N	S	T	R	U	14	C	15	2	16	8	1	17	0	4	4	18	3	19	L	20	0	21	0	0	0	22	Y	23	N	24	L	25	C	1	4	7	26		
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50						
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE										COMP. SUBCODE		VALVE SUBCODE		LER/NO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.		ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRO-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 The chilled water thermostat on the A chiller was set too low causing

1 1 the chiller to trip. The chiller was restarted and the chilled water

1 2 temperature controller was readjusted.

1 3

1 4

1	5	X	28	0	0	0	29	Mode 3	30	A	31	Operator observation	32	NA	33	NA	34	NA	35	NA	36	NA	37	0	0	0	38	Z	39	NA	40	0	0	0	41	NA	42	Z	43	NA	44	N	45	NA	46	NA	47	NA	48	NA	49	NA	50
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50										
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION		ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE		PERSONNEL EXPOSURES NUMBER		TYPE		DESCRIPTION		PERSONNEL INJURIES NUMBER		DESCRIPTION		LOSS OF OR DAMAGE TO FACILITY TYPE		DESCRIPTION		PUBLICITY ISSUED		DESCRIPTION		NRC USE ONLY																	

NAME OF PREPARER R. W. OuellettePHONE: (704) 373-7530