



Wisconsin Electric POWER COMPANY
231 WEST MICHIGAN, MILWAUKEE, WISCONSIN 53201

DTMB/LEK

July 16, 1981

Mr. J. G. Keppler, Regional Director
Office of Inspection and Enforcement,
Region III
U. S. NUCLEAR REGULATORY COMMISSION
799 Roosevelt Road
Glen Ellyn, Illinois 50137

Dear Mr. Keppler:

DOCKET NO. 50-266
LICENSEE EVENT REPORT NO. 81-008/01T-0
POINT BEACH NUCLEAR PLANT, UNIT 1



Enclosed is Licensee Event Report No. 81-008/01T-0
(a 14-day follow-up report) with an attachment which provides
a description of an event reportable in accordance with
Technical Specification 15.6.9.2.A.3, "Abnormal degradation
discovered in fuel cladding, reactor coolant pressure boundary,
or primary containment."

Please note that the 24-hour written notification
was incorrectly numbered 007 instead of 008.

Very truly yours,

Executive Vice President

Sol Burstein

Enclosure

Copies to NRC Resident Inspector
C. F. Riederer (PSCW)
Peter Anderson (WED)

IE22
5
1/1

JUL 17 1981