

LICENSEE EVENT REPORT

CONTROL BLOCK

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01	M	D	C	C	N	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5
LICENSEE CODE					LICENSE NUMBER					LICENSE TYPE					CAT									

01	L	5	0	5	0	0	0	3	1	8	7	0	6	0	9	8	1	5	0	7	0	9	8	1	9
REPORT SOURCE					DOCKET NUMBER					EVENT DATE					REPORT DATE										

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

At 1025 during surveillance testing, RPS Channel "A" trip unit for Thermal Margin/Low Pressure Monitor was found to be faulty (T.S. 3.3.1.1). The trip unit was replaced, the new trip unit was tested and put back into operation at 1155. The three redundant Thermal Margin/Low Pressure channels remained operable during this event. No similar events have been reported.

09	I	A	E	E	I	N	S	T	R	U	X	Z	
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE	
11		12		13		14				15		16	
17		18		19		20				21		22	
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE				REPORT TYPE		REVISION NO.	
23		24		25		26				27		28	
29		30		31		32				33		34	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.	
35		36		37		38		39		40		41	
42		43		44		45		46		47		48	
PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER		REVISION NO.		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.	
49		50		51		52		53		54		55	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

Bistable Trip Unit ATU7 would not trip at appropriate signal levels. The assembly was replaced with a spare and was sent to the supplier for repair. A high rate of failure of this type of instrument has not been attained. Surveillance tests are conducted monthly. No additional preventive action is deemed necessary.

1E	E	1	0	0	NA	B	Surveillance Testing
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY	
29		30		31		32	
33		34		35		36	
ACTIVITY CONTENT		AMOUNT OF ACTIVITY		LOCATION OF RELEASE		DISCOVERY DESCRIPTION	
37		38		39		40	
41		42		43		44	
PERSONNEL EXPOSURES		PERSONNEL INJURIES		LOSS OF OR DAMAGE TO FACILITY		PUBL CITY	
45		46		47		48	
49		50		51		52	
53		54		55		56	
57		58		59		60	
61		62		63		64	
65		66		67		68	
69		70		71		72	
73		74		75		76	
77		78		79		80	
81		82		83		84	
85		86		87		88	
89		90		91		92	
93		94		95		96	
97		98		99		100	

8107240203 810709
PDR ADOCK 05000312
S PDR

NRC USE ONLY

NAME OF PREPARER M. A. Junge/P. G. Rizzo

PHONE (301) 269-4747/4786