

Mailing Address

Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Alabama 35291
Telephone 205 783-6081

F. L. Clayton, Jr.
Senior Vice President
Flintridge Building

OFFICIAL COPY

MB



Alabama Power

the southern electric system

June 18, 1981

Docket No. 50-348

Mr. J. P. O'Reilly
U. S. Nuclear Regulatory Commission
Region II, Suite 3100
101 Marietta Street, N.W.
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

I.E. BULLETIN 79-02
FARLEY NUCLEAR PLANT UNIT 1

During the second refueling outage, Alabama Power Company completed an anchor bolt upgrade program. There are now fewer than 5% of the concrete expansion anchor bolts with safety factors less than the bulletin requirements on any system within the scope of the program. Alabama Power Company believes these actions have brought Farley Unit 1 into full compliance with the bulletin requirements.

Very truly yours,

F. L. Clayton Jr.
F. L. Clayton, Jr.

FLCJr/RSF:de

cc: Mr. R. A. Thomas
Mr. G. F. Trowbridge
Mr. E. A. Reeves
Mr. W. H. Bradford
Office of I & E
Division of Reactor Operations Inspection
Washington, D. C.

IE11
3
1/0

8107240445 810618
PDR ADOCK 05000348
Q PDR