

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

June 22, 1981

TELEPHONE: AREA 704
373-4083

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303




Re: RII:JPO
Docket Nos. 50-269, -270, -287
IE Bulletin 81-01

Dear Mr. O'Reilly:

In regard to the subject bulletin transmitted by your letter dated January 27, 1981, Duke Power Company has completed an inspection of the Oconee Unit 1, Unit 2, and Unit 3 accessible mechanical snubbers. This inspection was completed by May 31, 1981. The results of the inspection were satisfactory for all three units. Only one safety-related mechanical snubber, No. 3-07A-6-0-2400A-H78, was discovered "locked-up." This snubber is located on the Unit 3 LP Condensate System. This letter supplements my letter of March 20, 1981.

I declare under penalty of perjury that the statements set forth herein are true and correct to the best of my knowledge, executed on June 22, 1981.

Very truly yours,


William O. Parker, Jr.

JLJ:scs

IE11
5
1/0