

400 Chestnut Street Tower II

July 2, 1981

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

OFFICE OF INSPECTION AND ENFORCEMENT BULLETIN 80-18 - NRC-OIE REGION II
LETTER RII:JPO 50-327, SEQUOYAH NUCLEAR PLANT UNITS 1 AND 2 - SUPPLEMENTAL
RESPONSE

On October 16, 1980, TVA responded to your letter dated July 24, 1980
which transmitted IE Bulletin 80-18 on Adequate Minimum Flow Through
Centrifugal Charging Pumps. A supplemental response was submitted on
November 17, 1980.

The modifications described in our October 16, 1980 response to the
bulletin were determined to constitute an unreviewed safety question
(USQ) in accordance with 10 CFR 50.59. We notified NRC-NRR of this
determination on November 18, 1980 and requested that they approve the
implementation of the modification for Sequoyah unit 1. R. L. Tedesco's
letter dated June 29, 1981 to H. G. Parris provided approval.

The modifications described in my October 16, 1980 letter will be imple-
mented on Sequoyah unit 1 during the next outage of sufficient duration.
The next planned outage for unit 1 is scheduled for September 1981. TVA
will have the modification implemented on Sequoyah unit 2 before initial
criticality.

If you have any questions, please get in touch with D. L. Lambert at
FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555



IE11
3
1/0

8107240534 810702
PDR ADDCK 05000327
Q PDR