



DMB/LER

Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

Designated
Original -

Certified by J.R. Maffei
Supv. Ofc. Asst
Division DRPI

July 20, 1981

Mr J G Keppler
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Operation of Reactor Water Cleanup System
With Inoperable Isolation Valve

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reported in compliance with Technical Specification 6.7.B.2.c. Inadequate procedural controls resulted in failure to recognize the Technical Specification requirements applicable to this particular inoperable valve.

David Muscarella

L O Mayer, PE
Manager of Nuclear Support Services

LOM/DMM/jh

cc: Director, IE, USNRC (30)
Director, MIPC, USNRC (3)
NRC Resident Inspector
MPCA
Attn: J W Ferman



-over-

IE22
5/1

8107280174 810720
PDR ADOCK 05000263
S PDR

JUL 23 1981