

**Detroit
Edison**

Donald A. Wells
Manager-Quality Assurance
(313) 237-9657

2000 Second Avenue
Detroit, Michigan 48226
(313) 237-8000



July 14, 1981
EF2-53570

Mr. James G. Keppler, Director
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: Interim Report of 10CFR50.55(e) Item on Non-Seismic Equipment
Over Seismic (#26)

Dear Mr. Keppler:

The final report on the Non-Seismic Equipment over seismic problem cannot be submitted to you by July 14, 1981, as scheduled. This additional interim report is to provide you with the current status of the evaluation of this problem.

The problem was originally reported to Mr. J. Konklin of NRC-Region III by Mr. R.W. Barr, Detroit Edison Project Quality Assurance Director, by telephone on January 18, 1980. It had been noted, at that time, that non-seismic equipment was erected over and/or in close proximity to safety related equipment.

Edison Engineering had identified the affected equipment as non-seismic pieces of HVAC duct located in the Reactor and Auxiliary Buildings. The problem did not exist in the RHR complex, as all HVAC duct work there has been seismically designed; nor does it exist in other Fermi 2 buildings such as the Turbine or Radwaste Buildings, as no safety related equipment is located there.

A redesign of supports in the problem areas will be necessary. A contract to do this work has been awarded to Giffels Associates, Inc. Giffels is presently conducting a study on the ducts, and an actual reanalysis of duct hangers will be started in July. Where electrical cable trays are involved Sargent and Lundy is performing the work under existing contracts. After the redesign is completed the required construction work will be scheduled as construction schedules allow.

Another report on this item, either interim or final, is scheduled to be sent to you on or before November 11, 1981. If you have any questions concerning this matter, please contact Mr. H.A. Walker, Supervisor-Construction Quality Assurance.

Very truly yours,

DAW/HAW/cp

IE21
S 1/0
JUL 24 1981

8107300141 810714
PDR ADOCK 05000341
S PDR

Mr. James G. Keppler, Director
Page Two

July 14, 1981
EF2-52570

cc: Mr. Victor Stello, Jr., Director
Office of Inspection and Enforcement
Division of Reactor Inspection Programs
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. Bruce Little, Resident Inspector
U.S. Nuclear Regulatory Commission
Resident Inspectors Office
6450 North Dixie Highway
Newport, Michigan 48166