

OFFICIAL COPY

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

July 2, 1981

TELEPHONE: AREA 704
373-4183

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303



Re: McGuire Nuclear Station Unit 1
Docket No. 50-369

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-369/81-94. This report concerns Technical Specification 3.3.3.8; "The Radioactive Liquid Effluent Monitoring Instrumentation Channels shown in Table 3.3-12 shall be operable." This incident was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

A handwritten signature in cursive script that reads "William O. Parker, Jr." followed by a stylized flourish.

William O. Parker, Jr.

FBN:pw
Attachment

cc: Director
Office of Management & Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. Bill Lavallo
Nuclear Safety Analysis Center
Post Office Box 10412
Palo Alto, CA 94303

Ms. M. J. Graham
Resident Inspector - NRC
McGuire Nuclear Station

IE22
S1/1