

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37402


1750 Chestnut Street Tower II

OFFICIAL COPY

June 26, 1981

31 JUL 7 A7:53

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKET
NO. 50-327 - FACILITY OPERATING LICENSE DPR-77 - REPORTABLE OCCURRENCE
REPORT SQRO-50-327/81062

The enclosed report provides details concerning the inoperability of the turbine-driven auxiliary feedwater pump. This event caused unit 1 to enter action statement "A" of limiting condition for operation 3.7.1.2 and is reported as required by Sequoyah unit 1 Technical Specification 6.9.1.13.b.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. A. Green
H. J. Green
Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. Bill Lavallee
Nuclear Safety Analysis Center
Palo Alto, California 94303

NRC Inspector, Sequoyah

IE22
5/1

8108030139 810625
PDR ADDCK 05000327
S PDR