

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

OFFICIAL COPY

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

July 20, 1981

TELEPHONE: AREA 704
373-4083

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303




Re: Catawba Nuclear Station
Unit 1
Docket No. 50-413

Dear Mr. O'Reilly:

In regard to my June 15, 1981 letter which transmitted Significant Deficiency Report SD-413/81-10, due to the complexities of the training and the number of people involved, Corrective Actions 4 and 5 as noted in the letter will now be completed by August 14, 1981.

Very truly yours,



William O. Parker, Jr.

RWO/php

cc: Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

NRC Resident Inspector
Catawba Nuclear Station

IE27
51/0