

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37460 REGION II

1750 Chestnut Street Tower II

OFFICIAL COPY

June 30, 1981

JUN 7 4 30 PM '81

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKET
NO. 50-327 - FACILITY OPERATING LICENSE DPR-77 - REPORTABLE OCCURRENCE
REPORT SQRO-50-327/81021 REVISION 1

The enclosed report is a revision to my letter dated March 11, 1981, concerning the stopping of reactor coolant pumps 1 and 2 with reactor coolant pumps 3 and 4 and residual heat removal pump B also out of service. The original event required entry into limiting conditions for operation 3.4.1.3.a and 3.4.1.3.b and was reported under Sequoyah unit 1 Technical Specification 6.9.1.13.b. This revised report provides additional information regarding the inadvertent initiation of residual heat removal containment spray.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. A. Green
H. J. Green

Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. Bill Lavalley
Nuclear Safety Analysis Center
Palo Alto, California 94303

NRC Inspector, Sequoyah

IE22
5/11