

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

31 JUL 29 AIO: 30

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

July 23, 1981

TELEPHONE: AREA 704  
373-4083

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Re: RII:JPO  
50-269, -270, -287  
IE Bulletin 80-23



Dear Sir:

My letter of December 29, 1980, in response to subject IE Bulletin, stated that Duke would replace the existing Valcor solenoid valves at Oconee with Asco solenoid valves. Duke has re-evaluated this commitment and has decided to replace the coils of the Valcor solenoid valves rather than the entire valve.

The effort to implement this change is in progress and will be completed on all Oconee units as soon as possible.

Very truly yours,

William O. Parker, Jr.

RLG/php

cc: Director  
Division of Reactor Operations Inspection  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

IE11  
3  
1/0

8108040057 810723  
PDR ADDCK 05000269  
G PDR

27