

OFFICIAL COPY

# DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

July 24, 1981

TELEPHONE: AREA 704  
373-4083

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303


Re: Oconee Nuclear Station  
Docket No. 50-269



Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-269/81-12. This report is submitted pursuant to Oconee Nuclear Station Technical Specification 6.6.2.1.b(2), which concerns operation in a degraded mode permitted by a limiting condition for operation, and describes an incident which is considered to be of no significance with respect to its effect on the health and safety of the public.

Very truly yours,

  
William O. Parker, Jr.

JLJ:eck  
Attachment

cc: Director  
Office of Management & Program Analysis  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. Bill Lavallee  
Nuclear Safety Analysis Center  
P. O. Box 10412  
Palo Alto, California 94303

Mr. F. Jape  
Resident Inspector  
Oconee Nuclear Station

IE22  
S  
1/1

8108040480 810724  
PDR ADOCK 05000269  
S PDR