

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401  
500A Chestnut Street Tower II

March 24, 1981

OFFICIAL COPY

*E. J. [unclear]*

11-28 02:01

81-040-032

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 -  
DOCKET NO. 50-327 - FACILITY OPERATING LICENSE DPR-77 - 10 CFR 21 REPORT

This is to supplement the subject report transmitted to you dated March 20, 1981. All unit 1 ERCW and CCS valve operator switch compartment heaters were disconnected by March 12, except for five on the ERCW system. These five switch housings did not indicate any damage, and their compartment heaters were disconnected by March 19.

This was reported by Walter E. Andrews to the Sequoyah IE resident inspector, Ed Ford, on March 24, 1981.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

*James R. Parris*

H. G. Parris  
Manager of Power

IE19  
s  
1/0

IE19

8108070146 810324  
PDR ADOCK 05000327  
S PDR