

TENNESSEE VALLEY AUTHORITY REGION


CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

July 28, 1981

31 JUL 30 AID: 50

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Region II - Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNIT 2 - WELDING OF STRUCTURAL STEEL ANNULUS FLOOR  
FRAMING - NCR 1173 - SIXTH INTERIM REPORT

The subject nonconformance was initially reported to NRC-OIE Inspector R. W. Wright on April 15, 1980, in accordance with 10 CFR 50.55(e). This was followed by our interim reports dated May 15, July 30, and November 7, 1980, and February 20 and June 23, 1981. TVA is continuing the reinspection of the welds identified for sampling by MIL-Standard 105D. We expect to submit our next written report by October 29, 1981.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager  
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Jr., Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

IE27  
51/0

8108100315 810728  
PDR ADOCK 05000439  
S PDR