

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	J	S	G	S	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			6	
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	31	CAT	35

REPORT SOURCE 0 1 7 8

DOCKET NUMBER 1 6 0 5 0 0 0 3 1 1 7 68

EVENT DATE 0 7 0 1 8 74

REPORT DATE 0 7 3 1 8 1 9 75 80

0 2 | On July 1, 1981, after a Unit 2 outage period in which both the inner and outer

0 3 | containment air lock doors were open, containment integrity was established without

0 4 | performing the surveillance procedure as required by technical specification

0 5 | 4.6.1.3.b.

0 6 |

0 7 |

0 8 |

09		S A		A 12		A 13		Z Z Z Z Z Z				Z 14		Z 15		Z 16	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24
LER RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
17		8 1		0 5 3		0 3		L		0							
21		22		23		24		25		26		27		28		29	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
H 18 Z 19		Z 20		Z 21		0 0 0 0		Y 22		N 23		Z 24		Z 25		Z 9 9 9 26	
33		34		35		36		37		40		41		42		43	

1 0 | Personnel error. The operators overlooked the Unit 2 containment air lock surveil-

1 1 | lance procedure because it was new, and different than the Unit 1 procedure. The

1 2 | surveillance procedure was completed immediately upon discovery it had been missed.

1 3 | All personnel involved were counseled on the difference between Unit 1 and Unit 2

1 4 | containment air lock surveillance and their importance. (81-39)

FACILITY STATUS (1) 5 (2) B (28) % POWER (3) 0 (4) 3 (5) 0 (29) OTHER STATUS (30) N/A METHOD OF DISCOVERY (31) A (32) Operator Observation DISCOVERY DESCRIPTION (32)

ACTIVITY CONTENT (33) 1 (34) 2 (35) 2 (36) NA AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES									
NUMBER		TYPE		DESCRIPTION					
1	7	0	0	0	37	2	38	NA	

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	40	NA

LOSS OF OR DAMAGE TO FACILITY (43)
TYPE DESCRIPTION
1 9 2 (42) NA

PUBLICITY								NRC USE ONLY															
ISSUED		DESCRIPTION																					
2	0	N	(44)	NA																			

NRC USE ONLY

NAME OF ORDERER
8108110467 810731
PDR ADCK 05000311
S PDR

Frank Dickey

PHONE 609-935-5100