

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

USNRC REGION 3
ATLANTA, GEORGIA

1750 Chestnut Street Tower II

August 4, 1981

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKET
NO. 50-327 - FACILITY OPERATING LICENSE DPR-77 - REPORTABLE OCCURRENCE
REPORT SQRO-50-327/81079

The enclosed report provides details concerning the inoperability of the
liquid radwaste effluent monitor (O-RM-90-122) which caused Sequoyah unit 1
to enter action statement 30 of limiting condition for operation 3.3.3.9
and is reported under Technical Specification 6.9.1.13.b.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. A. Green
H. J. Green
Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. Bill Lavalley
Nuclear Safety Analysis Center
Palo Alto, California 94303

NRC Inspector, Sequoyah

IF22
S1/1

8108130229 810804
PDR ADOCK 05000327
S PDR