

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | ALJMF2 | 200-000000-00 | 3411111 | 411111 | 5

REPORT SOURCE L605000364707148180806811 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 | At 0525 on 7/14/81, while performing FNP-2-STP-20.0 (Penetration Room Exhaust and Air
03 | Filtration Train A (B) Operability Test), the A Train Penetration Room Filtration System
04 | was declared inoperable when the associated exhaust fan damper (3356 A) failed to open.
05 | Tech. Spec. 3.7.8 requires two independent penetration room filtration systems to be
06 | operable. Tech. Spec. 3.7.8 action statement requirements were met. Health/safety of
07 | the public was not affected.

08 | 9

| | | | | | |
|--|---|--|--|---|--|
| SYSTEM CODE | CAUSE CODE | CAUSE SUBCODE | COMPONENT CODE | COMP. SUBCODE | VALVE SUBCODE |
| S H 11 | E 12 | B 13 | V A L V O P 14 | E 15 | Z 16 |
| EVENT YEAR | SEQUENTIAL REPORT NO. | OCCURRENCE CODE | REPORT TYPE | REVISION NO. | |
| 8 1 | 0 2 7 | 0 3 | L | 0 | |
| ACTION TAKEN | FUTURE ACTION | EFFECT ON PLANT | SHUTDOWN METHOD | HOURS | ATTACHMENT SUBMITTED |
| C 18 | Z 19 | Z 20 | Z 21 | 0 0 0 0 | N 23 |
| | | | | | NPRD-4 FORM SUB. |
| | | | | | N 24 |
| | | | | | PRIME COMP. SUPPLIER |
| | | | | | A 25 |
| | | | | | COMPONENT MANUFACTURER |
| | | | | | P 3 4 0 26 |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 | The event was caused by a faulty solenoid valve. The valve was replaced and following
11 | successful completion of FNP-2-STP-20.0, the A Train Penetration Room Filtration System
12 | was returned to service at 1650 on 7/14/81.

13 | 4

14 | 5

FACILITY STATUS E28 | % POWER 08829 | OTHER STATUS NA30 | METHOD OF DISCOVERY B31 | DISCOVERY DESCRIPTION Surveillance Test32

ACTIVITY CONTENT Z33 | RELEASED OF RELEASE Z34 | AMOUNT OF ACTIVITY NA35 | LOCATION OF RELEASE NA36

PERSONNEL EXPOSURES NUMBER 00037 | TYPE Z38 | DESCRIPTION NA39

PERSONNEL INJURIES NUMBER 00040 | DESCRIPTION NA41

LOSS OF OR DAMAGE TO FACILITY TYPE Z42 | DESCRIPTION NA43

PUBLICITY ISSUED DESCRIPTION N44 | NA45

8108130235 810806
 PDR AD0CK 05000364
 S PDR ARER W. G. Hairston, III
 (205) 899-5156