



Commonwealth Edison
Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920

DMB/LEK

August 24, 1981

DJS LTR #81-674

James G. Keppler, Regional Director
Directorate of Regulatory Operations Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137



Reportable Occurrence Report #81-49/01T-0, Docket #050-237 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.1.(b), operation of the unit or affected systems when any parameter or operation subject to a limiting condition is less conservative than the least conservative aspect of the limiting condition for operation established in the technical specifications.

DJSwtl

D. J. Scott
Station Superintendent
Dresden Nuclear Power Station

DJS:lg

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
U.S. NRC, Document Mgt. Branch
File/NRC

*IE22
5/1*

8109030116 810824
PDR ADOCK 05000237
S PDR

AUG 27 1981



Commonwealth Edison

DEVIATION REPORT

DVR NO. STA UNIT YEAR NO.
D-12 - 2 - 81 - 89

PART 1 TITLE OF DEVIATION

MSIV 1A and 1D Failure to Meet Closure Timing Requirements

OCCURRED
8/14/81 1640
DATE TIME

SYSTEM AFFECTED 203

PLANT CONDITIONS

Main Steam

MODE

Run

PWR(MWT)

1174

LOAD(MWE)

329

TESTING

☒ YES ☐ NO

DESCRIPTION OF EVENT

While performing DOS 250-2, both MSIV 1A and 1D closed in less than the 3 seconds required by Tech. Spec. Table 3.7.1.

DESCRIPTION OF CAUSE

OTHER APPLICABLE INFORMATION

NRC notified via ENS phone at 1714. Shutdown was already in progress.

EQUIPMENT ☒ YES
FAILURE ☐ NO

DR NO.

WR NO.

D15203

Jim Doxsey

8/14/81

RESPONSIBLE SUPERVISOR

DATE

PART 2 OPERATING ENGINEERS COMMENTS

The MSIV's were adjusted and retimed satisfactorily. Times were 3.7 sec. on 1D and 3.4 sec on 1A after adjustment. Previously they were 2.1 sec. on MSIV 1A, and 1.7 sec. on MSIV 1D.

TYPE OF DEVIATION
REPORTABLE OCCURRENCE

☒ 14 DAY ☐ 10CFR21☐ 30 DAY NOTIFICATION
6.6.B.1.bEVENT OF POTENTIAL
PUBLIC INTERESTTECH SPEC
VIOLATIONNON-REPORTABLE
OCCURRENCEANNUAL
REPORTINGYES ☒NO ☐SAFETY-
RELATED
WR ISSUEDYES ☒NO ☐REPORTABLE OCCURRENCE
NUMBER

XX- 81-49/0FT-0

ACTION ITEM NO.

PROMPT ON-SITE NOTIFICATION

R. M. Ragan

8/14/81

1700

TITLE

DATE

TIME

TITLE

DATE

TIME

24-HOUR NRC NOTIFICATION

☒ TPH ENS Phone 8/14/81 1714☐ TGM M. Jordan 8/17/81 0948

REGION III DATE TIME

☒ TGM J. Keppler 8/17/81 1350

REGION III & DOL DATE TIME

PROMPT OFF-SITE NOTIFICATION

F. A. Palmer 8/17/81 1420

TITLE

DATE

TIME

TITLE

DATE

TIME

RESPONSIBLE COMPANY OFFICER INFORMED OF 10CFR21
CONDITIONS AND THEIR REPORT TO NRC

TITLE

DATE

TIME

REVIEW AND COMPLETED

T. Lang

8/17/81

OPERATING ENGINEER

DATE

ACCEPTANCE BY STATION REVIEW
AS REQUIRED

DATE

RESOLUTION APPROVED AND
AUTHORIZED FOR DISTRIBUTION

J. Brunner
8/25/81

John W. Dwyer
8/25/81

Douglas Scott
STATION SUPERINTENDENT

8/25/81
DATE