

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK: 1

1 T N S N P 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT No

NT
1 REPORT SOURCE L 6 0 5 10 0 0 3 2 7 7 0 7 3 1 8 1 8 0 8 2 7 8 1 9
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

2 At 1730 CDT on 7/31/81, with Unit 1 at 100% RTP, the temperature recorder (1-TR-61-
3 138) for the ice condenser temperature monitoring system was observed to be operating
4 erratically rendering the ice condenser monitoring system inoperable. The unit
5 complied with the action statement for LCO 3.6.5.2. There was no effect on public
6 health or safety. No previous occurrences.
7
8

9 S R 11 E 12 E 13 I N S T R U 14 R 15 Z 16
9 SYSTEM CODE 10 CAUSE CODE 11 CAUSE SUBCODE 12 COMPONENT CODE 13 COMP. SUBCODE 14 VALVE SUBCODE 15
17 LER/RO REPORT NUMBER 18 1 19 1 20 1 21 1 22 1 23 1 24 0 9 8 25 0 3 26 0 3 27 L 28 0 29 0 30 0 31 0 32 0
21 EVENT YEAR 22 23 24 SEQUENTIAL REPORT NO. 25 OCCURRENCE CODE 26 REPORT TYPE 27 REVISION NO.
33 E 34 X 35 Z 36 Z 37 0 0 0 0 38 N 39 N 40 L 41 W 1 3 0
33 ACTION TAKEN 34 FUTURE ACTION 35 EFFECT ON PLANT 36 SHUTDOWN METHOD 37 HOURS 38 ATTACHMENT SUBMITTED 39 NPD-4 FORM SUB. 40 PRIME COMP. SUPPLIER 41 COMPONENT MANUFACTURER
 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 42

43 The recorder failed due to a faulty selector switch. The switch contacts were
44 changed and the recorder was returned to service on 8/7/81. If subsequent operation
45 of the recorder results in frequent occurrences of this problem, the recorder will
46 be replaced or rebuilt.
47

48 E 49 1 0 0 0 50 NA 51 A 52 Operator observation
50 FACILITY STATUS 51 % POWER 52 OTHER STATUS 53 METHOD OF DISCOVERY 54 DISCOVERY DESCRIPTION
55 Z 56 Z 57 NA 58 NA 59 NA
55 ACTIVITY RELEASED 56 CONTENT OF RELEASE 57 AMOUNT OF ACTIVITY 58 LOCATION OF RELEASE
60 0 0 0 61 Z 62 NA
60 PERSONNEL EXPOSURES NUMBER 61 TYPE 62 DESCRIPTION
63 0 0 0 64 NA
63 PERSONNEL INJURIES NUMBER 64 DESCRIPTION
65 Z 66 NA
65 LOSS OF OR DAMAGE TO FACILITY TYPE 66 DESCRIPTION
67 N 68 NA
67 PUBLICITY ISSUED 68 DESCRIPTION
 8109080146 810827
 PDR ADDCK 05000327
 S PDR
68 69

Preparer: A. M. Wilkey/M. R. Harding

Phone: (615) 842-8317

NRC USE ONLY