

DAB/LER



September 4, 1981

L81-902
FILE: RR 2 (NP-33-81-52)

Docket No. 50-346
License No. NPF-3

Mr. James G. Keppler
Regional Director, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137



Dear Mr. Keppler:

Reportable Occurrence 81-046
Davis-Besse Nuclear Power Station, Unit 1
Date of Occurrence: August 7, 1981

Enclosed are three copies of Licensee Event Report 81-046 with supplemental information sheets which are being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Terry D. Murray

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station

TDM/ljk

Enclosure

cc: Mr. Victor Stello, Jr., Director
Office of Inspection and Enforcement
Encl: 30 copies

Mr. Norman Haller, Director
Office of Management and Program Analysis
Encl: 3 copies

Mr. Luis Reyes
NRC Resident Inspector
Encl: 1 copy

IE22
S11

8109150138 810904
PDR ADDCK 05000346
S PDR

EDISON PLAZA 300 MADISON AVENUE TOLEDO, OHIO 43652

SEP 10 1981