

NRC FORM 365
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE ARAN0100-0000-0000-0000
LICENSE NUMBER 00000000000000000000
LICENSE TYPE 11111
CAT 58

CON'T

REPORT SOURCE L05000313704088180813819
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
On 4-8-81 following a plant trip and on 7-7-81 following an inadvertent actuation signal, the steam driven emergency feedwater pump (P7A) started and was subsequently tripped by the turbine overspeed trip mechanism. In both cases, the electric motor driven EFW pump remained operable. The trip mechanism was reset, the pump tested and returned to service. Similar to ILLER 50-313/80-021. Reportable per Tech. Spec. 6.12.3.2.b.

SYSTEM CODE CH11 CAUSE CODE E12 CAUSE SUBCODE B13 COMPONENT CODE TURBINE14 COMP SURF CODE Z15 VALVE SUBCODE Z16

LER NO REPORT NUMBER 17 81 EVENT YEAR 21 SHUTDOWN METHOD Z20 EFFECT ON PLANT Z20 HOURS 22 0000 ATTACHMENT SUBMITTED N23 NPD-4 FORM SUB Y24 PRIME COMP SUPPLIER A25 COMPONENT MANUFACTURER T14726

ACTION TAKEN E18 X19 FUTURE ACTION X19 SEQUENTIAL REPORT NO 005 OCCURRENCE CODE 03 REPORT TYPE X REVISION NO 1

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
Following the 4-8-81 event, the mechanism for initiating the overspeed trip was adjusted to latch more firmly. An inspection following a similar event on 7-7-81 indicated the latch mechanism needs replacement for improved reliability - This will be accomplished upon receipt of new parts. Mechanical vibrations upon pump start are believed to be the cause of the trips. Evaluation of the problem is continuing.

FACILITY STATUS E28 % POWER 110029 OTHER STATUS NA METHOD OF DISCOVERY A31 DISCOVERY DESCRIPTION Operator Observation

ACTIVITY RELEASED OF RELEASE Z33 Z34 AMOUNT OF ACTIVITY NA LOCATION OF RELEASE NA

PERSONNEL EXPOSURES NUMBER 00037 TYPE Z38 DESCRIPTION NA

PERSONNEL INJURIES NUMBER 00040 DESCRIPTION NA

LOSS OF OR DAMAGE TO FACILITY TYPE Z47 DESCRIPTION NA

PUBLICITY ISSUED N44 DESCRIPTION NA

NRC USE ONLY

NAME OF PREPARER Thomas H. Cogburn

PHONE 501/968-2519

8109150377 810813
PDR ADCK 05000313
S PDR