

## LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N J S G S 2 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
8 9 LICENSEE CODE 13 15 LICENSE NUMBER 25 26 LICENSE TYPE JO 57 CAT 58

CON'T  
0 1 REPORT SOURCE L 6 0 5 0 0 0 3 1 1 7 0 6 1 6 8 1 8 0 6 3 0 S 1 9  
7 8 DOCKET NUMBER 58 59 EVENT DATE 74 75 REPORT DATE 80

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 During a repair of a valve bonnet leak, check valves 21MS46 and 23MS46 were found to  
0 3 be internally damaged. This occurrence constituted failure of one or more  
0 4 components which could prevent the fulfillment of the functional requirements of  
0 5 systems used to cope with accidents analyzed in the SAR in accordance with  
0 6 Technical Specification 6.9.1.8.e.

0 7  
0 8  
7 8 9

0 9 SYSTEM CODE C H 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE V A L V E X 14 COMP SUBCODE C 15 VALVE SUBCODE A 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20  
17 LER/RO REPORT NUMBER 8 1 21 22 SEQUENTIAL REPORT NO. 0 3 5 24 25 OCCURRENCE CODE 0 1 28 29 REPORT TYPE T 30 REVISION NO. 0 32  
ACTION TAKEN A 18 FUTURE ACTION A 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED Y 23 NPD-4 FORM SUB. N 24 PRIME COMP SUPPLIER L 25 COMPONENT MANUFACTURER V O 8 5 26  
33 34 35 36 37 38 39 40 41 42 43 44 45

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 Valves 21MS46 and 23MS46 were repaired on site by PSE&G personnel assisted by a  
1 1 vendor representative. Complete parts have been ordered for both valves. A  
1 2 supplemental report will be issued when investigation into the cause of this  
1 3 occurrence has been determined.

1 4  
7 8 9

1 5 FACILITY STATUS G 28 % POWER 0 0 0 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator Observation 32  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
1 6 ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 NA 35 AMOUNT OF ACTIVITY NA 36 LOCATION OF RELEASE NA 37  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

2 0 PUBLICITY ISSUED N 44 DESCRIPTION NA 45  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NRC USE ONLY

J. J. Espey

PHONE: 609-935-0998