

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLDG: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 AR AN 02 00 -0 00 00 00 -00 03 41 11 11 11 4 5

7 8 9 14 15 25 26 30 37 38

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T

01 0 5 0 0 0 3 6 8 0 7 1 4 8 1 0 8 1 1 8 1 9

7 8 60 61 68 69 74 75 80

REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During Mode 3 operation, following an inadvertant Emergency Core Cooling

03 System (ECCS) actuation from the Plant Protection System (PPS), Refueling

04 Water Tank discharge valve, 2CV-5630, opened on a Safety Injection Actuation

05 Signal (SIAS), but failed in the open position rendering it inoperable to

06 a Recirculation Actuation Signal. There have been no similar occurrences.

07 Reportable per T.S. 6.9.1.9.b.

08

7 8 9

09 SL F 11 E 12 A 13 V A I L V I O P 14 A 15 Z 16

7 8 9 11 12 13 14 15 16 17 18 19 20

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE

17 8 1 0 2 6 0 3 L 0

21 22 23 24 25 26 27 28 29 30

LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.

18 A 19 Z 9 2 20 2 21 0 0 0 0 N 23 Y 24 A 25 R 3 7 8 26

33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

ACTION FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED FOR SUB PRIME COMP SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The open limit switch on the valve operator failed to stop valve travel

11 on SIAS and the motor burned up. The valve operator motor was replaced

12 and the limit switches readjusted. The independent ECCS flowpath was

13 returned to operable status meeting the requirements of T.S. 3.5.2.

14 Action Statement a.

7 8 9

15 D 28 0 0 0 29 NA A 31 Operation observation 32

7 8 9 10 11 12 13 14 15 16 17 18 19 20

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

16 Z 33 Z 34 NA NA NA 36

7 8 9 10 11 12 13 14 15 16 17 18 19 20

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

17 0 0 0 37 Z 38 NA 39

7 8 9 10 11 12 13 14 15 16 17 18 19 20

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

18 0 0 0 40 NA 41

7 8 9 10 11 12 13 14 15 16 17 18 19 20

PERSONNEL INJURIES NUMBER DESCRIPTION

19 Z 42 NA 43

7 8 9 10 11 12 13 14 15 16 17 18 19 20

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

20 N 44 NA 45

7 8 9 10 11 12 13 14 15 16 17 18 19 20

PUBLICITY ISSUED DESCRIPTION

20 N 44 NA 45

7 8 9 10 11 12 13 14 15 16 17 18 19 20

NRC USE ONLY

NAME OF PREPARER Chris N. Shively

PHONE 501/968-2519