

WISCONSIN PUBLIC SERVICE CORPORATION



P.O. Box 1200, Green Bay, Wisconsin 54305

September 4, 1981

Mr. J. G. Keppler, Regional Director
Office of Inspection & Enforcement
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr. Keppler:

Docket 50-305

Operating License DPR-43

IE Bulletin 81-02 Supplement 1; Failure of Gate Type Valves to Close Against Differential Pressure

In accordance with the requirement of IE Bulletin 81-02 Supplement 1, Failure of Gate Type Valves to Close Against Differential Pressure, an investigation was undertaken to determine whether this type valve was in any safety-related system or component in the Kewaunee Plant. Results of the investigation revealed that the Kewaunee Plant has no Westinghouse Electro-Mechanical Division (W - EMD) motor operated gate valves other than those reported in response to IE Bulletin 81-02. Therefore, Bulletin 81-02 Supplement 1 is not applicable for our facility.

The review effort and associated documentation for this bulletin required approximately 10 manhours.

Very truly yours,

E. R. Mathews

E. R. Mathews, Senior Vice President
Power Supply and Engineering

snf

cc - Mr. Robert Nelson, NRC Resident Inspector
Dir - Office of Inspection & Enforcement

Subscribed and Sworn to
Before Me This 4th Day
of September 1981

Susan A. Fox
Notary Public, State of Wisconsin



IE 11
5
1/0

My Commission Expires: March 24, 1985

8109150543 810904
PDR ADDCK 05000305
Q FJR

SEP 8 1981