

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower 11

September 8, 1981

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 2 - DOCKET  
NO. 50-328 - FACILITY OPERATING LICENSE DPR-79 - REPORTABLE OCCURRENCE  
REPORT SQRO-50-328/81104

The enclosed report provides details concerning three containment spray  
test line return isolation valves to the refueling water storage tank  
being found open. This event required entry into limiting conditions  
for operation 3.6.2.1 and 3.0.3 and is reported under Sequoyah unit 2  
Technical Specification 6.9.1.12.f. Attached to the LER is additional  
information in the form of a report prepared by a TVA investigation team.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

*P.R. Waller*

*for* H. J. Green  
Director of Nuclear Power



Enclosures (3)

cc (Enclosures):

Director (3)

Office of Management Information and Program Control  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Director (40)

Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Mr. Bill Lavalley  
Nuclear Safety Analysis Center  
Palo Alto, California 94303

NRC Inspector, Sequoyah

8109150576 810908  
PDR ADOCK 05000328  
S PDR

An Equal Opportunity Employer

IE27  
5/11