

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

September 11, 1981

TELEPHONE: AREA 704
373-4083

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: Catawba Nuclear Station
Unit 1
Docket No. 50-413



Dear Mr. O'Reilly:

On August 12, 1981 your office was notified of a potentially reportable item pursuant to 10 CFR 50.55(e). The significant deficiency report SD 413/81-18 concerning damage to a Kerotest active valve was to be submitted by September 11, 1981. At this time the evaluation of the damage has not been completed. The evaluation will be completed and the report will be submitted by October 12, 1981.

Very truly yours,

William O. Parker, Jr.
William O. Parker, Jr. *By [Signature]*

RWO:ls

cc: Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Resident Inspector
Nuclear Regulatory Commission
Catawba Nuclear Station

IE27
5
1/6

8109220404 810911
PDR ADOCK 05000413
S PDR