

## (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	N	M	P	1	2	0	0	-	0	0	0	0	p	p	p	3	4	1	1	1	1	4			5	
7	8	11 LICENSEE CODE							14	15 LICENSE NUMBER										25	26 LICENSE TYPE					30	57	CAT	58

0	1	REPORT SOURCE	L	6	0	5	0	0	0	2	2	0	7	0	8	3	1	8	1	8	0	9	1	0	8	1	9
7	8		60	61	DOCKET NUMBER								68	69	EVENT DATE					74	75	REPORT DATE					80

0 2 During a weekly environmental radiation monitor surveillance inspection, it was found  
0 3 that only six monitors were functioning. Environmental tech specs require a minimum  
0 4 of seven. Of the total of ten monitors, four failed over a three day period. All  
0 5 monitors had been functioning at the previous weekly check. There were no adverse  
0 6 consequences due to this event.  
0 7  
0 8

SYSTEM CODE 0 9		CAUSE CODE B A		CAUSE SUBCODE E		COMPONENT CODE I N S T R U				COMP. SUBCODE E		VALVE SUBCODE Z					
7	8	9	10	11	12	13	14	15	16	17	18	19	20				
LER/RO REPORT NUMBER 17		EVENT YEAR 8 1		SEQUENTIAL REPORT NO. 0 4 2		OCCURRENCE CODE 0 4		REPORT TYPE T		REVISION NO. 0							
21	22	23	24	25	26	27	28	29	30	31	32						
ACTION TAKEN B		FUTURE ACTION Z		EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED N		NPRD-4 FORM SUB. N		PRIME COMP. SUPPLIER L		COMPONENT MANUFACTURER G 0 8 0	
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50

1 0 The cause of this occurrence was defective power supply units. The reason four out of

1 1 ten monitors suffered power supply failures is unknown. A portable monitor was

1 2 installed the following day to place the site in compliance with environmental tech

1 3 specs.

1 4

8 9  
FACILITY STATUS  
1 5 E 28  
2 8 9  
10 11 12 13  
% POWER 1 0 0 29  
OTHER STATUS NA 30  
44  
METHOD OF DISCOVERY B 31  
45 46  
DISCOVERY DESCRIPTION SURVEILLANCE TEST 32  
80

ACTIVITY CONTENT  
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)

1 6 Z (33) Z (34) NA

LOCATION OF RELEASE (36)

NA

PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION
1	7	000	(37) Z	(38) NA (39)

PERSONNEL INJURIES	
NUMBER	DESCRIPTION
000	NA

1	9	2	42	NA	43
---	---	---	----	----	----

8 9 10  
 PUBLICATION 8109220415 810910  
 ISSUED DESCRIPTION (45) PDR ADOCK 05000220  
 (2) 0 (44) NA S PDR  
 NRC USE ONLY  
 68 69 80

NAME OF PREPARER Robert Randall

PHONE: (315) 343-2110 1596