

# LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 F L C R P 3 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

01 L 0 5 0 - 0 3 0 2 7 0 8 1 5 8 1 8 0 9 1 6 8 1 9

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 | At 1000, during normal operation, it was discovered that atmospheric radiation monitor

03 | RM-A5 was inoperable. This created an event contrary to T.S. 3.7.7.1. At 1615 on

04 | 9/3/81, it was determined T.S. 3.0.3 was applicable to the occurrence, but operation

05 | did not comply with requirements. There was no effect upon the health or safety

06 | of the general public. This was the sixth occurrence for RM-A5, and this is the

07 | eighth event reported under this Specification.

08 |

09 S G 11 E 12 B 13 P U M P X X 14 H 15 Z 16

17 8 1 - 0 5 6 0 1 T - 0

A X Z Z 0 0 0 Y N A T 3 0 0

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 | The cause of this event is attributed to failure of the sample vacuum pump. The

11 | pump failed due to broken carbon vanes in the pump. Grab samples were initiated.

12 | The pump was repaired and functionally tested. Engineering evaluation REI 79-10-9

13 | is investigating pump failures. Modification MAR 80-2-7 will initiate full emergency

14 | recirc upon initiation of a flow alarm for RM-A5.

15 E 1 0 0 NA A Operator observation

16 Z Z NA NA LOCATION OF RELEASE

17 0 0 0 Z NA

18 0 0 0 NA

19 Z NA

20 Z NA

21 NA

22 NA

23 NA

24 NA

25 NA

26 NA

27 NA

28 NA

29 NA

30 NA

31 NA

32 NA

33 NA

34 NA

35 NA

36 NA

37 NA

38 NA

39 NA

40 NA

41 NA

42 NA

43 NA

44 NA

45 NA

46 NA

47 NA

48 NA

49 NA

50 NA

51 NA

52 NA

53 NA

54 NA

55 NA

56 NA

57 NA

58 NA

59 NA

60 NA

61 NA

62 NA

63 NA

64 NA

65 NA

66 NA

67 NA

68 NA

69 NA

70 NA

71 NA

72 NA

73 NA

74 NA

75 NA

76 NA

77 NA

78 NA

79 NA

80 NA

81 NA

82 NA

83 NA

84 NA

85 NA

86 NA

87 NA

88 NA

89 NA

90 NA

91 NA

92 NA

93 NA

94 NA

95 NA

96 NA

97 NA

98 NA

99 NA

100 NA

8109240498 810916  
PDR ADDCK 05000302  
S PDR

NAME OF PREPARER *Victor A. Hernandez* (SEE ATTACHED SUPPLEMENTARY INFORMATION SHEET)

PHONE: 904/795-6486

NRC USE ONLY

GPO 917-926