

100-21-112-35

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

September 18, 1981

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 2 - DOCKET  
NO. 50-328 - FACILITY OPERATING LICENSE DPR-79 - REPORTABLE OCCURRENCE  
REPORT SQRO-50-328/810106

The enclosed report provides details concerning the inoperability of the  
containment gaseous and particulate radiation monitors (2-RE-90-106  
and 112) due to an overcurrent trip. This report is submitted in accordance  
with Sequoyah unit 2 Technical Specification 5.9.1.13.b.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

*J. A. Conner*  
H. J. Green  
Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)  
Office of Management Information and Program Control  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Director (40)  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Mr. Bill Lavalley  
Nuclear Safety Analysis Center  
Palo Alto, California 94303

NRC Inspector, Sequoyah

IE22  
5  
1/1

8109240564 810918  
PDR ADOCK 05000328  
S PDR