

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N J O C P 1 0 0 - 0 0 0 0 - 0 0 4 1 1 1 1 4 5
7 8 9 0 14 15 25 26 30 37 CAT 58

CON'T
0 1 REPORT SOURCE L 6 0 5 0 0 0 2 1 9 7 0 8 2 8 8 1 8 0 9 1 1 8 1 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2 On August 28, 1981, at approximately 0720, the 'B' Stack Gas Pump was found
0 3 tripped. The low flow alarm did not annunciate to give an indication of
0 4 the situation. The 'A' pump was put in service at 0740. During the event the
0 5 ventilation system radiation monitors did not indicate any abnormalities.
0 6 The other influents to the stack were secured, therefore, the safety sign-
0 7 ificance of the event is considered minimal.
0 8
0 9

SYSTEM CODE 11 M C 12 E 13 F 14 P U M A X 15 H 16 Z
9 10 11 12 13 18 19 20

CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
17 LER NO. REPORT NUMBER 21 8 1 22 23 24 0 4 2 25 26 27 28 0 3 29 30 T 31 32 0
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
18 A 19 F 20 Z 21 Z 22 0 0 0 0 23 Y 24 N 25 N 26 G 0 4 6
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0 The cause of the event was attributed to a malfunction of the automatic
1 1 lubrication system and a component failure on the low flow switch alarm
1 2 card. The pump was rebuilt and tested. The alarm card was replaced.
1 3 A new Stack Gas Monitoring System is scheduled to be installed in the
1 4 beginning of 1982. The existing pumps will be replaced and the operator's
7 8 9 tour sheet will be upgraded.

FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32
1 5 H 28 0 0 0 29 NA A 31 Operator Observation
7 8 9 10 11 12 13 44 45 46 80

ACTIVITY RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
1 6 Z 33 Z 34 NA NA
7 8 9 10 11 12 13 44 45 46 80

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39
1 7 0 0 0 37 Z 38 NA
7 8 9 10 11 12 13 44 45 46 80

PERSONNEL INJURIES NUMBER DESCRIPTION 41
1 8 0 0 0 40 NA
7 8 9 10 11 12 13 44 45 46 80

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43
1 9 Z 42 NA
7 8 9 10 11 12 13 44 45 46 80

PUBLICITY ISSUED DESCRIPTION 45
2 8109290305 810911
7 PDR ADOCK 05000219
S PDR

Weekly News Release
F. X. Sullivan
NRC USE ONLY
68 69 80
609-693-6037
PHONE: