

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	C	B	E	P	2	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4		5
7	8	9	LICENSEE CODE				14	15	LICENSE NUMBER				25	26	LICENSE TYPE				30	57	CAT		58				

CON'T

0	1	L	6	0	5	0	-	0	3	2	4	7	0	8	2	8	8	1	8	0	9	1	7	8	1	9
7	8	REPORT SOURCE		60	61	DOCKET NUMBER				58	69	EVENT DATE				74	75	REPORT DATE				80				

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

During plant operation, while performing routine maintenance on RHR steam leak detection temperature switches, 2-Ell-TS-N600A and B, the HPCI system automatically isolated due to the receipt of a HPCI isolation trip signal "A." At the time of this event the LPCI and ADS systems were operable. This event did not affect the health and safety of the public.

Technical Specifications 3.3.2, 3.5.1, 6.9.1.9b

0	9	S	D	A	C	I	N	S	T	R	U	E	Z								
7	8	9	10	11	12	13	14	15	16	17	18	19	20								
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.											
17		8 1		0 7 9		0 3		L		0											
21		22		23		24		25		26											
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER					
18		19		20		21		22		23		24		25		26					
33		34		35		36		37		40		41		42		43		44		47	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

Accidental removal of the thermocouple leads to HPCI room ambient temperature switch 2-E41-N602A, Model 86, by the technician performing the N600A and B maintenance, caused this event. Within five minutes of the event the N602A leads were reconnected and the HPCI system was reset and returned to operability. The technician has been counseled to be sure of his identification of plant equipment prior to performing any work or maintenance.

1	5	F	0	8	9	NA	A	Operational Event	
7	8	9	10	11	12	13	14	15	
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
28		29		30		31		32	

1	6	Z	Z	NA	NA	LOCATION OF RELEASE	
7	8	9	10	11	12	13	
ACTIVITY		CONTENT		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
33		34		35		36	

1	7	0	0	0	Z	NA	
7	8	9	10	11	12	13	
PERSONNEL EXPOSURES		TYPE		DESCRIPTION			
37		38		39		40	

1	8	0	0	0		NA	
7	8	9	10	11	12	13	
PERSONNEL INJURIES		TYPE		DESCRIPTION			
41		42		43		44	

1	9	Z				NA	
7	8	9	10	11	12	13	
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION			
45		46		47		48	

2	0	N				NA	
7	8	9	10	11	12	13	
PUBLICITY		DESCRIPTION		ISSUED		NRC USE ONLY	
49		50		51		52	

8109290398 810917
PDR ADOCK 05000324
S PDR

NAME OF PREPARER M. J. Pastva, Jr.

PHONE: 919-457-9521