




ARKANSAS POWER & LIGHT COMPANY
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

September 3, 1981

1CAN098101

Mr. G. L. Madsen, Chief
Reactor Operations & Nuclear Support
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011



Subject: Arkansas Nuclear One - Unit 1
Docket No. 50-313
License No. DPR-51
Licensee Event Report No.
81-010/03L-0
(File: 0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 1 Technical Specification 6.12.3.2.a, attached is the subject report concerning an error found in a channel B amplifier gain setting associated with the Reactor Protective System.

Very truly yours,

David C. Trimble

David C. Trimble
Manager, Licensing

DCT:GAC:lfw

Attachment

cc: Mr. Victor Stello, Jr., Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. Norman M. Haller, Director
Office of Management & Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

IE22
S
1/1

8109290434 810903
PDR ADDCK 05000313
S PDR

MEMBER MIDDLE SOUTH UTILITIES SYSTEM

IE22