



Carolina Power & Light Company

Brunswick Nuclear Project
P. O. Box 10429
Southport, NC 28461-0429

March 19, 1990

FILE: B09-13510C
SERIAL: BSEP/90-0238

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555

BRUNSWICK STEAM ELECTRIC PLANT UNIT 2
DOCKET NO. 50-324
LICENSE NO. DPR-62
SPECIAL REPORT PER TECHNICAL SPECIFICATION 3.7.8 AND
PURSUANT TO TECHNICAL SPECIFICATION 6.9.2 (2-SR-90-002)

Gentlemen:

During Unit 2 Refuel 8 and maintenance outage, a Unit 2 fire barrier Limiting Condition for Operation (LCO) was initiated, at 0800 hours February 14, 1990, for fire door no. 206, located at penetration seal no. R2-2-070, the south door of the Reactor Building 20' elevation mini-steam tunnel. The LCO was initiated to permit MAC test equipment cords to be run into the area. Due to the scope of the involved work, the seven-day time frame of the LCO was exceeded on February 21, 1990. Restoration of the door to functional status was completed on March 8, 1990. Until cancellation of the LCO, the required fire watches remained in effect.

Very truly yours,

G. L. Harness, General Manager
Brunswick Nuclear Project

TMJ/mcg

Enclosure

cc: Mr. S. D. Ebnetter
Mr. E. G. Tourigny
BSEP NRC Resident Office

9003280078 900319
PDR ADOCK 05000324
S PDC