

New Hampshire Yankee

Ted C. Feigenbaum
Senior Vice President and
Chief Operating Officer

NYN-90076

March 21, 1990

United States Nuclear Regulatory Commission
Washington, DC 20555

Attention: Document Control Desk

- References:
- (a) Facility Operating License No. NPF-67, Docket No. 50-443
 - (b) Facility Operating License No. NPF-86, Docket No. 50-443
 - (c) USNRC Letter dated December 28, 1989, "Revisions to Seabrook Technical Specifications", V. Nerses to E. A. Brown
 - (d) New Hampshire Yankee Letter NYN-90004 dated January 4, 1990, "Certification of Seabrook Station Unit 1 Technical Specifications", T. C. Feigenbaum to USNRC
 - (e) USNRC Letter dated March 15, 1990, "Issuance of Facility Operating License NPF-86 - Seabrook Station, Unit No. 1", S. A. Varga to E. A. Brown

Subject: Inoperability of Seismic Monitor

Gentlemen:

Revised Technical Specification Tables 3.3-7 and 4.3-4 were provided via Reference (c) and certified via Reference (d). These revised tables reflected the relocation of Triaxial Seismic Response Spectrum Recorder 1-SM-XR-6708 from the 4 foot to the 22 foot elevation in the Service Water Pump House.

On February 9, 1990, this monitor was moved to this new location. This instrument, although capable of performing its intended function, could not be considered operable pursuant to the requirements of the existing Seabrook Station Technical Specification 3.3.3.3 due to this relocation. This monitor was returned to operable status on March 15, 1990, when revised Technical Specifications were issued via Reference (e).

9003290063 900321
FDR ADOCK 05000443
S PDC

New Hampshire Yankee Division of Public Service Company of New Hampshire
P.O. Box 300 • Seabrook, NH 03874 • Telephone (603) 474-9521

1/0
IE22
A001


United States Nuclear Regulatory Commission
Attention: Document Control Desk

March 21, 1990
Page two

This monitor was inoperable for a period exceeding 30 days. This report is, therefore, being provided in accordance with the requirements of Technical Specifications 3.3.3.3 and 6.8.2.

Should you have any questions regarding this matter, please contact Mr. Richard R. Belanger at (603) 474-9521, extension 4048.

Very truly yours,



Ted C. Feigenbaum

cc: Mr. William T. Russell
Regional Administrator
United States Nuclear Regulatory Commission
Region I
475 Allendale Road
King of Prussia, PA 19406

Mr. Victor Nerses, Project Manager
Project Directorate I-3
United States Nuclear Regulatory Commission
Division of Reactor Projects
Washington, DC 20555

Mr. Noel Dudley
NRC Senior Resident Inspector
P.O. Box 1149
Seabrook, NH 03874