

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	8		3
7	8	9	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 4

7 8 9 10 68 69 80

PUBLICITY
ISSUED DESCRIPTION (45)
2 0 N (44) NA
NRC USE ONLY

PHONE 447-1791 X4424

NORTHEAST UTILITIES



THE CONNECTICUT LIGHT AND POWER COMPANY
THE HARTFORD ELECTRIC LIGHT COMPANY
WESTERN MASSACHUSETTS ELECTRIC COMPANY
HILVORE WATER POWER COMPANY
NORTHEAST UTILITIES SERVICE COMPANY
NORTHEAST NUCLEAR ENERGY COMPANY

P.O. BOX 270
HARTFORD, CONNECTICUT 06101
(203) 666-6911

June 22, 1983
MP-5144

Dr. Thomas E. Murley
Regional Administrator, Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Reference: Facility Operating License No. DPR-65
Docket No. 50-336
Reportable Occurrence RO 50-336/83-16/03X-1

Dear Dr. Murley:

This letter forwards the Licensee Event Report 83-016/03X-1 required to be submitted within thirty days pursuant to Millstone Unit 2 Appendix A Technical Specifications, Section 6.9.1.9.b, conditions leading to operation in a degraded mode permitted by a limiting condition. This update LER is being submitted to clarify additional corrective actions for LER 83-016/03L-0. An additional three copies of the report are enclosed.

Yours truly,

NORTHEAST NUCLEAR ENERGY COMPANY

A handwritten signature in cursive script, appearing to read 'E. J. Mroczka'.

E. J. Mroczka
Station Superintendent
Millstone Nuclear Power Station

EJM/TF:mr

Attachment: LER RO 50-336/83-16/03X-1

cc: Director, Office of Inspection and Enforcement, Washington, D. C. (30)
Director, Office of Management Information and Program Control,
Washington, D. C. (3)
U. S. Nuclear Regulatory Commission, c/o Document Management Branch,
Washington, D. C. 20555

IE 22
11