




KANSAS GAS AND ELECTRIC COMPANY

GLENN L. KOESTER
VICE PRESIDENT - NUCLEAR

June 24, 1983

Mr. W.C. Seidle, Chief
Reactor Projects Branch 2
U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011



KMLNRC 83-077

Re: Docket No. STN 50-482

Ref: 1) Interim Report KMLNRC 83-016 dated 2/17/83
from GLKoester, KG&E, to WCSeidle, NRC
2) Interim Report KMLNRC 83-050 dated 4/25/83
from GLKoester, KG&E, to WCSeidle, NRC

Subj: Interim Potential 10CFR50.55(e) Report -
Discrepancies in the BN System

Dear Mr. Seidle:

This letter provides an interim report on a potential 10CFR50.55(e) item concerning documentation and hardware discrepancies in the Borated Refueling Water System (BN). This matter was initially reported pursuant to 10CFR50.55(e) on January 21, 1983, and interim reports were provided in References 1) and 2).

The identified BN documentation and hardware discrepancies have been evaluated and none would have adversely affected the safety of operations had they gone uncorrected. However, Kansas Gas and Electric Company will not close this potential 10CFR50.55(e) item until more of the previously turned-over safety-related systems have been reverified and evaluated.

A final or interim report on this matter will be submitted to you on or before September 30, 1983. In the interim, please direct any questions concerning this subject to me or to Mr. Otto Maynard of my staff.

Yours very truly,

Glenn L. Koester

GLK:bb

cc: RCDeYoung
HRoberts/WSchum

8307050087 830624
PDR ADOCK 05000482
S PDR

IE-27
1/8