



LOUISIANA
POWER & LIGHT


142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

June 29, 1983

W3I83-0218
Q-3-A35.07.33

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 33
"Chilled Water Piping Supports"
Seventh Interim Report



REFERENCE: LP&L letter W3I83-0163 dated May 11, 1983

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report to the USNRC no later than June 30, 1983.

At the present time, all corrective action is complete. DCN-MP-459 has been signed off by the contractor as complete along with supporting documentation. This documentation is currently under review by LP&L and Ebasco. This review is expected to be complete by early July, 1983.

A Final Report will be submitted to the USNRC by July 29, 1983.

Very truly yours,

F. J. Drummond
Project Support Manager - Nuclear

FJD/RWP/MAL:keh

cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

3) Mr. E. L. Blake

2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

4) Mr. W. M. Stevenson

8307120202 830629
PDR ADOCK 05000382
S PDR

1/0 IE-27