

Washington Public Power Supply System

P.O. Box 968 3000 George Washington Way Richland, Washington 99352 (509) 372-5000

RECEIVED
MTC

1983 JUL -5 PM 12:37

REGION VICE

June 29, 1983
G01-83-344

Nuclear Regulatory Commission
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596

Attention: Mr. D.M. Sternberg, Chief
Reactor Projects Branch No. 1

Subject: NUCLEAR PROJECT NO. 4
DOCKET NO. 50-513 REPORTABLE 10CFR50.55 (e)
ROCKBESTOS CABLE

Reference: 1) Telecon ME Rodin, Supply System to
PP Narbut, Region V, Nuclear Regulatory Commission,
dated January 26, 1982
2) G01-82-0060, dated February 26, 1982,
DW Mazur to RH Faulkenberry
3) G01-82-0152, dated April 21, 1982,
RW Root to RH Faulkenberry
4) G01-82-0413, dated July 2, 1982,
DW Mazur to R.H. Faulkenberry

Reference 3) informed your office of a reportable deficiency under 10CFR50.55(e), and transmitted an interim status report on the subject condition.

Reference 4) provided the Supply System's final report on the above caption condition. Since it has been determined that the only cable involved is that used in the Unit 4 penetrations (see reference 4) this letter only refers to Unit 4 and Docket No. 50-513.

Due to the current indeterminant status of Unit 4, a completion date has not yet been established. Therefore, we will defer any further updates until a completion schedule has been established or else no later than construction restart, whichever occurs first.

8307120241 830629
PDR ADOCK 05000513
S PDR

110 IE-27

Mr. D.M. Sternberg
Rockbestos Cable
Page 2
G01-83-344

If you have any questions or desire further information, please advise.



R.A. De Lorenzo,
Program Director WNP-1/4

RAD/GAB/cmh

cc: TA Mangelsdorf, Bechtel (860)
V. Mani, UE&C (897)
HW Kwan, UE&C (8U6)
A Toth, NRC (917Q)
V. Stello, Director of Inspection, NRC
FDCC (899)
ORM (847)