

Arizona Public Service Company

P.O. BOX 21666 • PHOENIX, ARIZONA 85036

RECEIVED
NRC

1983 AUG -1 PM 1:56

July 21, 1983
ANPP-27290-RQT/BSK

REGION V

50-528

U.S. Nuclear Regulatory Commission
Region V
Creskide Oaks Office Park
1450 Maria Lane - Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. D. M. Sternberg, Chief
Reactor Projects Branch 1

Subject: Time Extension for Report - DER 83-19
A 50.55(e) Potentially Reportable Deficiency Relating to
Safety Injection System Snubbers From Pacific Scientific Do
Not Function Properly.
File: 83-019-026, D.4.33.2.

Reference: (A) Telephone Conversation between A. D'Angelo and R. Tucker
on April 6, 1983.
(B) ANPP -23646 dated May 3, 1983 (Interim Report)


Dear Sir:

The NRC was notified of a potentially reportable deficiency in Reference (A), and an Interim Report was transmitted by Reference (B). At that time, it was estimated that a Final Report would be available by August 1, 1983.

Due to the extensive investigation and evaluation required, it is now expected that this information will be finalized by September 15, 1983, when a complete report will be submitted.

There is no new information or change to the Interim Report at this time.

Very truly yours,



E. E. Van Brunt, Jr.
APS Vice President
Nuclear Projects Management
ANPP Project Director

EEVBJr/RQT/rb

cc: See Page 2

U.S. Nuclear Regulatory Commission
Page 2

cc: Richard DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

T. G. Woods, Jr.
G. C. Andognini
J. A. Roedel
D. B. Fasnacht
A. C. Rogers
B. S. Kaplan
W. E. Ide
J. Vorees
J. R. Bynum
P. P. Klute/D. D. Green
A. C. Gehr
W. J. Stubblefield
W. G. Bingham
R. L. Patterson
R. W. Welcher
R. M. Grant
D. R. Hawkinson
L. E. Vorderbrueggen
G. A. Fiorelli
S. R. Frost
J. Self

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway - Suite 1500
Atlanta, Georgia 30339