

VIRGINIA ELECTRIC AND POWER COMPANY  
SURRY POWER STATION  
EMERGENCY PLAN IMPLEMENTING PROCEDURE

NUMBER	PROCEDURE TITLE	REVISION
EPIP-4.21	EVACUATION AND REMOTE ASSEMBLY AREA MONITORING (With 3 Attachments)	02
		PAGE 1 of 9

PURPOSE

Collect personnel dosimetry, monitor station personnel evacuating from the site, and decontaminate as necessary.

USER

Evacuation and remote assembly area monitoring.

ENTRY CONDITIONS

Any of the following:

1. Initiation by EPIP-4.01, Radiological Assessment Director Controlling Procedure;  
OR
2. Initiation by EPIP-4.02, Radiation Protection Supervisor Controlling Procedure.

REVISION RECORD

REV. 00	PAGE(S): Entire Procedure	DATE: 07-29-82
REV. 01	PAGE(S): 1 of 9, 4 of 9	DATE: 02-24-83
REV. 02	PAGE(S): 1 of 9, 4 of 9; Attachment 1, page 1 of 1	DATE: AUG 15 1983
REV.	PAGE(S):	DATE:
REV.	PAGE(S):	DATE:
REV.	PAGE(S):	DATE:
REV.	PAGE(S):	DATE:

APPROVAL RECOMMENDED

QC REVIEW

*[Signature]*  
8307080281 830831  
PDR ADOCK 05000280  
F PDR

APPROVED

*[Signature]*  
CHAIRMAN STATION NUCLEAR SAFETY  
AND OPERATING COMMITTEE

DATE

AUG 15 1983

X065



VIRGINIA ELECTRIC AND POWER COMPANY

Surry Power Station  
P. O. Box 315  
Surry, Virginia 23883

August 18, 1983

SURRY POWER STATION EMERGENCY PLAN IMPLEMENTING PROCEDURES

Enclosed are corrections to recently revised pages to the Surry Power Station Emergency Plan Implementing Procedures. Please take the following actions in order to keep your manual updated with the most recent revisions and their proper dates.

EPIP-4.21

Evacuation and Remote Assembly Area Monitoring

Remove and Destroy

Enter

Page 1 of 9

Page 1 of 9

E. P. DeWandel  
Records Management Supervisor

EPD/dkp

Attachments

X005  
1/1