

BOSTON EDISON COMPANY  
800 BOYLSTON STREET  
BOSTON, MASSACHUSETTS 02199

WILLIAM D. HARRINGTON  
SENIOR VICE PRESIDENT  
NUCLEAR

September 2, 1983

BECC 83-233

Mr. Domenic B. Vassallo, Chief  
Operating Reactors Branch #2  
Division of Licensing  
Office of Nuclear Reactor Regulation  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

License No. DPR-35  
Docket No. 50-293

Revision to Boston Edison Company letter dated May 13, 1983

Dear Sir:

In our letter of May 13, 1983, we stated that we intended to issue interim guidance to appropriate plant personnel concerning Boston Edison's position on TAP 1 C.O. This approach was taken because we did not believe we could integrate our I.C.6 policy into an existing Nuclear Operations Procedure (NOP) by August 12, 1983.

This letter is to apprise you of our decision not to issue the guidance and the reason for not doing so. The integration was accomplished early, and the NOP containing I.C.6 was issued June 17, 1983, making the interim guidance unnecessary.

Should you wish further information concerning this issue, please contact us.

Very truly yours,

*W D Harrington*

PMK/mat

*A001  
1/0*

8309090461 830902  
PDR ADDCK 05000293  
P PDR