

ILLINOIS POWER

CLINTON POWER STATION, P.O. BOX 678, CLINTON, ILLINOIS 61727-0678, TELEPHONE (217) 935-8881

U. 601840
L30-91(05-20)-LP
1A.120

May 20, 1991

Docket No. 50-461


Document Control Desk
Nuclear Regulatory Commission
Washington, D.C. 20555

Subject: Inservice Inspection Summary Report

Dear Sir:

In accordance with ASME Section XI, Article IWA-6000, Illinois Power Company (IP) is submitting the Inservice Inspection Summary Report. This summary report addresses the Inservice Inspection activities performed at Clinton Power Station between May 29, 1989 and March 9, 1991.

Sincerely yours,



F. A. Spangenberg, III
Manager, Licensing and Safety

WSI/alh

Attachment

cc: NRC Clinton Licensing Project Manager
NRC Resident Office
NRC Region III, Regional Administrator
Illinois Department of Nuclear Safety

9105310186 910520
PDR ADOCK 05000461
Q PDR

A047



INSERVICE INSPECTION SUMMARY REPORT

REPORT DATE: MAY 9, 1991

INSERVICE DATE: APRIL 24, 1987

REFUELING OUTAGE: RF-2

CLINTON POWER STATION

P.O. BOX 678 RT. 54 E. CLINTON, ILLINOIS 61727