

LICENSEE EVENT REPORT

CONTROL BLOCK:

							(1)
--	--	--	--	--	--	--	-----

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	D	C	C	N	1	2	0	0	-	0	0	0	0	0	0	0	0	3	4	1	1	1	1	1	1	4	5				
7	8	LICENSEE CODE						14	15	LICENSE NUMBER											25	26	LICENSE TYPE						30	57	CAT	58	5

CON'T

REPORT SOURCE: 01 L 05000317700067881006789
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During normal operation the Control Room Operator discovered the contain-

0 3 | ment atmosphere particulate monitor failed low at 0800. Corrective

0 4 | action was taken immediately and the monitor was returned to service at

0 5 | 1025. The containment atmosphere gaseous activity monitor and sump

0 6 | alarm systems remained operable throughout this event. This is not a

0 7 | repetitive occurrence.

7 8 9 SYSTEM CODE 10 11 CAUSE CODE 12 13 CAUSE SUBCODE 14 15 COMPONENT CODE 16 17 VALVE SUBCODE

(17)	LER RO REPORT NUMBER	[EVENT YEAR 7 8 21 22]	[— 23]	SEQUENTIAL REPORT NO.	[0 2 3 24 25 26]	[✓ 27]	OCCURRENCE CODE	[0 3 28 29]	REPORT TYPE	[L — 30 31]	REVISION NO.	[0 32]
ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER				
[B 18 33 34]	[Z 19 35 36]	[Z 20 37 38]	[Z 21 39 40]	[0 0 0 0 41 42 43 44]	[N 23 45 46]	[N 24 47 48]	[A 25 49 50]	[W 1 2 0 51 52 53 54]				

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Discovered moisture and some corrosion on scintillation tube and tube
1 1 | socket. The moisture was determined to be the result of a high ambient
1 2 | containment humidity and subsequent condensation inside the detector
1 3 | pig. Tube and socket were cleaned, tube reconnected, and particulate
1 4 | detector returned to service. No further corrective action necessary.

FACILITY STATUS (1) 5 (2) 5 (3) 28
 % POWER (4) 0 (5) 9 (6) 8 (7) 29
 OTHER STATUS (8) 30 N/A
 METHOD OF DISCOVERY (9) A (10) 31
 DISCOVERY DESCRIPTION (11) 32 Operator Observation

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 2 (33) 2 (34) N/A N/A

PERSONNEL EXPOSURES		
NUMBER	TYPE	DESCRIPTION
17	00	37 Z 38 N/A

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
0	0	0	40
		N/A	

1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52																																																									

LPDR

PUBLICITY
ISSUED DESCRIPTION (45)

2	0		(44)	N/A		WHO USE ONLY	8 7
---	---	--	------	-----	--	--------------	--------

7810110124

PDR ADCK ØST-317 S 781006

PHONE: 301.234-7043/7060

100