



November 28, 1978

L78-902

FILE: RR 2 (NP-33-78-55 &  
NP-33-78-84)

Docket No. 50-346  
License No. NPF-3

Mr. James G. Keppler  
Regional Director, Region III  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Enclosed are three copies of Licensee Event Report 78-045 and the supplemental information sheet for Licensee Event Report 78-070, which have been revised. The revisions to these reports are indicated by a "1" in the left margin.

Please replace Licensee Event Report 78-045 and the supplemental information sheet for Licensee Event Report 78-070 with the attached revised copies. The respective supplemental information sheet for 78-045 and Licensee Event Report form for 78-070 have not been revised and should be retained.

Yours truly,

Terry D. Murray  
Station Superintendent  
Davis-Besse Nuclear Power Station Unit 1

TDM/ljk

Enclosure

cc: Dr. Ernst Volgenau, Director  
Office of Inspection and Enforcement  
Encl: 30 copies

Mr. William G. McDonald, Director  
Office of Management Information  
and Program Control  
Encl: 3 copies

7812050157

A002  
3/11

5