



November 30, 1978

L78-907

FILE: RR 2 (NP-33-78-127)

Docket No. 50-346
License No. NPF-3

Mr. James G. Keppler
Regional Director, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Reportable Occurrence 78-111
Davis-Besse Nuclear Power Station Unit 1
Date of Occurrence: November 4, 1978

Enclosed are three copies of Licensee Event Report NP-33-78-127 with a supplemental information sheet which is being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the occurrence.

Yours truly,

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station

TDM/JRL/ljk

Enclosures

cc: Dr. Ernst Volgenau, Director
Office of Inspection and Enforcement
Encl: 30 copies LER 78-111

Mr. William G. McDonald, Director
Office of Management Information
and Program Control
Encl: 3 copies LER 78-111

78120701